

Minimizing Stray Magnetic Fields through Materials Selection

Using magnetic materials, components, and wiring layout that can generate magnetic fields must be minimized in constructing space flight hardware. Proper design and choice of manufacturing techniques can greatly reduce or eliminate stray magnetic fields.

General

- Keep electronic component lead lengths as short as possible.
- Avoid wiring loops and multiple ground paths.
- Use shielded wire or twisted pairs.

To reduce magnetic fields, avoid using ferro-magnetic materials for parts and structure whenever possible. The following is a categorized list of some commonly used structural and electronic materials:

NON-MAGNETIC		
Aluminum Alloy 30, 60, 90 Alloy 180 Beryllium Beryllium copper Brass Copper Carboloy	Germanium Gold Lead Magnesium alloys Manganin Moleculoy Molybdenum Neutroloy	Nickel Silver Phosphor bronze Protoloy Silver Tantalum Titanium Tungsten Zirconium

FEEBLY MAGNETIC	
Stainless steel 202 and 300 series	K-Monel Alloy 720

MAGNETIC		
Cobalt Copperweld Dumet Electroloy Elinvar Fenicoloy Ferrites Gridaloy M,P Iron	Invar Kovar Mesoloy Molypermalloy Mu metal Nichrome Nickel 200, 270 Nickel Iron Platinum+traces of Fe	Pelcaloy Permalloy R Monel Remendur (Fe-Co-V) Rodar (=kovar) Silicone steel 400 Series Stainless Supermalloy Vicalloy